Republic of the Philippines OFFICE OF THE SOLICITOR GENERAL 134 Amorsolo St., Legaspi Village Makati City **PURCHASE ÓRDER** 025-04-057 TOYOTA MAKATI, INC. UNDER THE TRADE NAME TOYOTA BICUTAN P.O. # Supplier: April 4, 2025 **PARAÑAQUE** KM. 15 West Service Road, South Super Highway, Sun Valley, Paranaque City Address: Mode of Procurement: 225-814-535-00000 TIN Negotiated Procurement - Small Value Procurement LBP-Pasong Tamo 1786-0902-33 Bank: Account No.: 02-7779485 (02) 8777-9500 Fax: Telephone Please furnish this Office the following articles subject to the terms and conditions contained herein: Delivery Term: Within 30 days upon receipt of Purchase Order OFFICE OF THE SOLICITOR GENERAL Place of Delivery Payment Term: Within 30 days upon final acceptance Date of Delivery: (Bank to Bank) Unit Cost Amount Description Unit Stock No. PREVENTIVE MAINTENANCE SERVICE (70,000 KM CHECK-UP) AND DIAGNOSIS, SUPPLY OF LABOR AND MATERIALS FOR REPAIR OF VEHICLE MODEL: TOYOTA INNOVA 2.0 E GAS A/T WITH PLATE NO. SLG 422 Scope of Works: Repair of Aircon System Diagnosis of Front Left Side Suspension 616.07 Php 985.71 Php 1.6 Clean and Adjust All Breaks hour 553.57 1,716.07 3.100 70,000 KM Check-Up hour 616.07 616.07 1.0 Toyota Car Care hour 616.07 616.07 1.0 Aircare Service hour 1,232.14 616.07 2.0 Recharge Freon hour 5,166.06 Php Subtotal: Parts: 67.86 67.86 piece Gasket 502.90 502.90 Oil Filter IMV piece 600.00 4 150.00 piece Plug, Spark 4.383.48 730.58 6 TGFS SN/CF 5W-30 1L liter 837.50 837.50 Gas Injector Cleaner 1 liter 194.20 194.20 Brake Cleaner 1 can 878.13 878.13 Toyota Geuine BACTAKLENZ (7ML) 1 millilite 295.31 295.31 1 Toyota Genuine Engine Room Cleaner can 305.80 1 305.80 Toyota Genuine Engine Room Coat can 3,660.94 3 660.94 can Aircon Cleaner 832.59 832.59 1 Element, Air Refiner lot Php 12.558.71 Subtotal: Sublet: 426.97 426.97 Shop Supplies and Materials 170.00 170.00 lot TMP POL & Inc. 1 725.00 1,450.00 2 Freon 134A lot 2,046.97 Php Subtotal MISC/Material: 1,071.43 1,071.43 1 X-1R Engine Treatment lot 1,071.43 Php Subtotal 5,166.06 Php Total Labor 12,558.71 Php **Total Parts:** 2,046.97 Php **Total Sublet** 1.071.43 Total MISC/Material Php Php 20.843.17 SUBTOTAL: 2,501.18 Php Note: Service provider must warrant that in case of defect in the repaired unit upon usage, it will be subject for repair/replacement, free of charge. The following shall be deemed to form and construed as part of the agreement I. Quotation II. Other documents as may be required by laws TWENTY THREE THOUSAND THREE HUNDRED FORTY FOUR AND 35/100 PESOS ONLY 23,344.35 Php Total Amount in Words: In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed. Very truly yours JESSICA L. CASTRO ENGR. RIC! Administrative Divisi Pro Service Toyota E Conforme: (Signature over printed name) EDITHA R. BUENDIA Director W, HRMAS ALOBS: 02-10/10/-2025-04-18 7 23 344.35 Amount: BIÑA