Republic of the Philippines

OFFICE OF THE SOLICITOR GENERAL

134 Amorsolo St., Legaspi Village Makati City

PURCHASE ORDER

Supplier:

Address:

TOYOTA MAKATI, INC. UNDER THE TRADE NAME TOYOTA

BICUTAN PARAÑAQUE

KM. 15 West Service Road, South Super Highway, Sun Valley, Parańaque

TIN:

225-814-535-00000

1786-0902-33

Bank:

P.O. # Date:

025-03-051

March 14, 2025

Mode of Procurement:

Negotiated Procurement - Small Value Procurement (53.9)

Gentlemen:

Account No.:

Telephone:

(02) 8777-9500

Fax:

02-7779485

LBP-Pasong Tamo

Please furnish this Office the following articles subject to the terms and conditions contained herein:

Place of Delivery: Date of Delivery:

OFFICE OF THE SOLICITOR GENERAL

Delivery Term: Within 30 days upon receipt of Purchase Order

Payment Term: Within 30 days upon final acceptance

			(Bank to Bank)				
Stock No.	Unit	Description	Qty.	Qty. Unit Cost		Amount	
		PREVENTIVE MAINTENANCE SERVICE: FOR 70,000 KM CHECK- UP FOR VEHICLE MODEL: TOYOTA COROLLA ALTIS 1.6G A/T WITH PLATE NO. ABP 1019/SAB 6339					
		Labor:					
	hr	70,000 KM CHECK-UP	3	Php 553.5	7 Php	1,660	
	hr	CLEAN AND ADJUST ALL BRAKES	1.6	616.0		985	
	hr	TIRE ROTATION/WHEEL BALANCING	1	616.0		616	
	hr	TOYOTA CAR CARE	0.840	616.0		517	
		Subtotal:			Php	3,779	
		Parts:					
	liter	GASKET	1	67.8	3	67	
	liter	OIL FILTER	1	372.7		372	
	liter	TGFS SN/CF 5W-30 1L	5	730.58	1	3,652	
	bottle	BREAK CLEANER	1	194.20		194	
	milliliter	TOYOTA GENUINE BACTAKLENZ (7ML)	i	878.13		878	
	liter	GAS INJECTOR CLEANER	1	837.50	1	837	
	liter	TOYOTA GENUINE ENGINE ROOM CLEANER	1	295.31		295.	
	liter	TOYOTA GENUINE ROOM COAT	1	305.80	1	305.	
		Subtotal:	.	000.00	Php	6,604.	
		Sublet:					
	lot	MISCELLANEOUS B	1	426.97		426.	
	lot	TMP POL & INC.	1	170.00		170.	
		Subtotal:	`	170.00	Php	596.	
		MISC/Material:					
	lot	X-1R ENGINE TREATMENT	1	1,071.43		1,071.	
		Subtotal:		3.00	Php	1,071.	
1		Total Labor:			Php	3,779.9	
		Total Parts:			Php	6,604.	
		Total Sublet:			Php	596.9	
		Total MISC/Material:			Php	1,071.4	
		SUBTOTAL:			Php	12,052.8	
		VAT:			Php	1,446.3	
		Note: Service provider must warrant that in case of defect in the repaired unit upon usage, it will be subject for repair/replacement, free of					
		charge.					
		The following shall be deemed to form and construed as part of the					
		agreement:					
		I. Quotation					
		II. Other documents as may be required by laws					
Amount in We	ordo:	 THIRTEEN THOUSAND FOUR HUNDRED NINETY NINE AND 2	1/100 DECC	CONIV	Bl	13,499.2	
Amount in W	orus.	INITIEEN INOUSAND FOUR HUNDRED NINE IT NINE AND 2	1/100 PESOS	ONLT	Php	13,499.2	

Php In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed.

Conforme:

A URIARTE ota Bicutan

(Signature over printed name)

0 (Date)

JESSICA L. CASTRO CAO, Administrative Divisi

EDITHA R. BUENDIA Director IV, HRMAS

Funds Available:

ALOBS:

02-101101-2028 - 03-126

Amount:

13,499.21

ARIEL J. UBIÑA Chief Accountant