

Request for Quotation

ax No.).		ion #:		June 20, 2022 PS-022-06-094		
Attention:							
	n: quote your lowest price on the items/s listed below, stating the short sentative.	test time		RODRIGO	L. OJENAL	signed by	
o be fille	ed-out by Supplier:			AO, Adminis			
TEM NO:	ITEM & DESCRIPTION	QTY	UNIT	BRAND	UNIT PRICE	TOTAL	
1	Diagnosis, Supply, Labor and Materials for Repair / Replacement / Repainting of Roof Panel, and Flooring of OSG Bus:	1	lot			PRICE	
z	For Vehicle Model: 2010 Hino Bus FG1JPUZ Initial Findings: For Repair of water leak For Repair / Replacement of rusted and corroded roof panel assy,						
×	including repainting of replaced parts For Repair / Replacement of partial flooring Estimated Material Quantities (but not limited to): 6 pcs. Marine plywood						
	1 pc. Tubular bar 1 pc. Plain G.I. sheet 80 pcs. Bolt and nut flat head 2x14 20 pcs. Bolt and nuts 1x12 1 gal. Rugby						
	Note: OSG Bus Service Vehicle with Plate No. SKL 815 assigned for Cavite Route						
	(Price Vat-Included)				Les Acres		
elivery P Varranty rice Valid							
		SIGN	IATURE	OF AUTHO	RIZED REPRES	ENTATIVI	
. Bidders	quote within days from the date of receipt/posting of RFQ. must submit current and valid documentary legal requirements upor's / Business Permit; EPS Registration Number: Membership: [] Pla		_	lled out quot	ation		
. [] Incon	ne / Business Tax Return (for P500K and above); ibus Sworn Statement for Small Value Procurement (for P50K and ers who have previously submitted the above legal requirements managements.	above);		uire its re-su	bmission.		
	certify under oath that I have personally conducted this canvass, wo frepresentative of the company submitting the quotation is genuin		e price/s	quoted are t	rue and correct,	and the	
				NNA LORA	X		

For more information, you may contact us:
Tel: (02) 8836-3314, (02) 8988-1674 loc 777
Telefore (03) 8813-1474

Telefax: (02) 8813-1174

Please send your quotation to:

osg.procurement2@gmail.com