

## **Request for Quotation**

To: Tel. No.: Fax No.			ion #:		June 20, 2022 PS-022-06-095	
Attention:						
	n: quote your lowest price on the items/s listed below, stating the short sentative.	test time		RODRIGO	L. OJENAL	signed by
o be fille	ed-out by Supplier:			AO, Adminis	strative Division	
TEM NO:		QTY	UNIT	BRAND	UNIT PRICE	TOTAL PRICE
. 1	Diagnosis, Supply, Labor and Materials for Repair / Replacement / Repainting of Roof Panel, and Flooring of OSG Bus: For Vehicle Model: 2010 Hino Bus FG1JPUZ	1	lot			THOL
z	Initial Findings: For Repair of water leak For Repair / Replacement of rusted and corroded roof panel assy, including repainting of replaced parts For Repair / Replacement of partial flooring					
	Estimated Material Quantities (but not limited to): 6 pcs. Marine plywood 1 pc. Tubular bar 1 pc. Plain G.I. sheet 80 pcs. Bolt and nut flat head 2x14 20 pcs. Bolt and nuts 1x12 1 gal. Rugby					
	Note: OSG Bus Service Vehicle with Plate No. SKE 781 assigned for Fairview Route  (Price Vat-Included)					
Delivery P Varranty Price Valid	eriod :					
lata		SIGN	IATURE	OF AUTHO	RIZED REPRES	ENTATIVE
. Bidders . [] Mayo . [] PhilG . [] Incom . [] Omni	quote within days from the date of receipt/posting of RFQ. must submit current and valid documentary legal requirements upon's / Business Permit; EPS Registration Number: Membership: [] Plaine / Business Tax Return (for P500K and above); bus Sworn Statement for Small Value Procurement (for P50K and above); ers who have previously submitted the above legal requirements many submitted the above legal requirements many submitted the subsequence of the submitted	tinum [ ]	Red			
Gir, I hereby	certify under oath that I have personally conducted this canvass, w	hich the				and the
			Al SIG	NNA LORA	F CANVASSER	

Tel: (02) 8836-3314, (02) 8988-1674 loc 777 Telefax: (02) 8813-1174

Telefax: (02) 8813-1174

Please send your quotation to:

osg.procurement2@gmail.com